



VĮ STATYBOS PRODUKCIJOS SERTIFIKAVIMO CENTRAS
Linkmenų str. 28, LT-08217 Vilnius, Lithuania
Notified body No. 1397



LIETUVOS
NACIONALINIS
AKREDITACIJOS
BIURAS

BANDYMAI
ISO/IEC 17025

Nr. LA. 01.103

Waste water treatment plant laboratory

TEST REPORT No. 1397-CPR-066/A.2
EN 12566-3:2005+A1:2009, Annex A, *watertightness*

2014-04-18

1. CLIENT: KLAASPLAST OÜ; adres Kuke talu, Kolu küla Kose vald Harjumaa, 75121 Estonia Reg. Nr. 11862070, contract No. NVI-48_2014 at 2014-03-12.
2. MANUFACTURER: KLAASPLAST OÜ, adres Kuke talu, Kolu küla Kose vald Harjumaa, 75121 Estonia Reg. Nr. 11862070.
3. SAMPLE: Small waste water treatment system (SWWTS) S4, material: glass reinforced plastic (GRP).
4. SAMPLE DELIVERY DATE: 2014-03-12.
5. TESTING LOCATION, ADDRESS AND DATE: Wastewater treatment plant laboratory Maišiagala, Vilnius district, 2014-03-12.
6. SAMPLING: Sampling was made by the Client. Sampling report No. 049-Klaasplast.
7. THE TEST MADE ACCORDING TO:
EN 12566-3:2005+A1:2009 Small wastewater treatment systems for up to 50 PT — Part 3: Packaged and/or site assembled domestic wastewater treatment plants, items 6.4.2 and annex A, item A.2 Water test.
8. TEST SPECIFICATIONS:
Plant was filled with pure water up to the top of the plant for 30 min.
9. TEST RESULTS.
There was no leakage from the SWWTS. The SWWTS is watertight.

This test report only certifies the characteristics of the sample submitted for testing.

Head of laboratory

Arnas Danila

Director



Robertas Encius